

QuickDrop

Set Up Instructions

DISPLAYS | **area**
by | EXHIBITS

Includes:

- Graphic with silver 3/8" grommets and pole pocket
- 5 Black Ball Bungees
- 5 Silver Hooks
- Black carry bag

Step 1:

Thread a black ball and bungee cord through each corner grommet on the QuickDrop graphic.



Step 2:

Loop the bungees at the top of the QuickDrop graphic over the booth's top corner pipes.

Fasten Bungee on one end then the other. A chair or ladder is recommended when doing this step.



NOTE: Use supplied hooks in grommets at top of graphic for additional graphic support.



Step 3:

Wrap the bungees at the bottom of the QuickDrop graphic around the bottom of the pipe. Place the knob of the bungee through the loop to fasten.

